


# FIELD INSPECTION REPORT

Date of Inspection: 18.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 0.500 km
Name of Road : LO 63 to Muschhari talu		
Scheme / Programme: MAINTENANCE		67547
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance
Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	/ M/A
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating : S

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

Ramesh Kumar Syl  
95

  
 18.12.2020  
 (Signature)

NAME:  
DESIGNATION :