

FIELD INSPECTION REPORT

| Date of Inspection: 18.12.2020 | | District: Samastipur |
|--|--|---|
| Division: RWD Dalsinghsarai | | Length(km): 1.900 |
| Name of Road : Mushehari talu to Dhania para Tola. | | |
| Scheme / Programme: MAINTENANCE | | CTSN: 67547 |
| Package No: | | Road Id No: |
| Status of the Project: Ongoing /Completed/Under Maintenance | | |
| Work is a case of: | | New Connectivity/ Up gradation/ Maintenance |
| Sl. No | Parameters to be Checked | Remarks |
| 1 | Pavement | |
| a) | Road Junction Condition | S |
| b) | Condition of Surfacing | S |
| c) | Riding Quality | S |
| d) | Road Camber | S |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | S |
| f) | Constraction Joint provided or not(CC Pavement) | S |
| g) | Compaction of flank/slope & raincuts if any | Some rain cuts |
| 2 | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S |
| b) | Condition of Abutment & Wing walls , Slab in RCC culverts | 1/11.11 |
| c) | Condition of railings/slab/approach for Bridge | |
| 3 | Road Furniture | |
| a) | Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | S |
| 4 | Compliance History | |
| a) | Status of ATR's & any others | NO |


Overall Rating :

S.P.L

| | |
|--|--|
| Satisfactory(S) | |
| Satisfactory but requires Improvement(SRI) | |
| Unsatisfactory(U) | |

Ramesh Kumar S/L

55


 18.12.2020
 (Signature)

NAME:

DESIGNATION :