

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020	District: Muzaffarpur
Division : Muzaffarpur East-1	Length (km): 3.029 KM
Name of the Road: NH-77 Siga Nangan Mahavidyalaya & Chandrabhatti to Kurhani Swathy Up Kendra	
Scheme/Programme: MAINTENANCE MMSy (SE)	
Package No.:	Road Id No.: 31572-01376
Status of the Project: Ongoing Completed Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating	☒ Satisfactory (S) ☐ Satisfactory but requires Improvement (SRI) ☐ Unsatisfactory (U)	S
----------------	---	---

NAME:

DESIGNATION:

17.12.2020
 Bajendra Kumar
 JE / RWD (W)
 Kurhani

K. Anand
 17/12/20
 (Signature)
 AE
 RWD (W)
 Kurhani