

FIELD INSPECTION REPORT

Date of Inspection : 18/12/2020	District: MV2
Division : R.W. 3 MV2 east 1	Length (km): 2.207 km
Name of the Road: Nargisnath Purney Road to Khairia via Harindapur	
Scheme/Programme: MAINTENANCE	mm 68y (Number of)
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes
g)	Compaction of flank/slope & raincuts if any	✓ Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Anil Kumar
18/12/2020
(Signature)

NAME:

DESIGNATION: