

# FIELD INSPECTION REPORT

Date of Inspection : 18/12/20 District: Munakherpur  
 Division : Munakherpur Ger-1 Length (km): 1.78 km  
 Name of the Road: Kanjarpur Road Alameda Kedarvishwa house to  
 Scheme/Programme: MAINTENANCE M.M. G. S. Retaining wall 40m  
 Package No.: Road Id No.:  
 Status of the Project: Ongoing/Completed/Under Maintenance  
 Work is a case of: New Connectivity/Up gradation/ Maintenance

| Sl. No. | Parameters to be checked                                                                                             | Remarks   |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------|
| 1.      | <b>Pavement</b>                                                                                                      |           |
| a)      | Road Junction condition                                                                                              | S/U       |
| b)      | Condition of Surfacing                                                                                               | S/U 3     |
| c)      | Riding Quality                                                                                                       | S/U       |
| d)      | Road Camber                                                                                                          | S/U       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No ✓  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓  |
| 2.      | <b>Cross Drainage</b>                                                                                                |           |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U ✓ |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U ✓ |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U ✓ |
| 3.      | <b>Road Furniture</b>                                                                                                |           |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓  |
| 4.      | <b>Compliance History</b>                                                                                            |           |
| a)      | Status of ATR's & any others                                                                                         | NO        |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

18/12/20  
 (Signature)

NAME:

DESIGNATION: