

FIELD INSPECTION REPORT

Date of Inspection :	18/12/2020	District:	MU 2
Division :	R.W. & MU 2 east 1	Length (km):	2.300 km
Name of the Road:	Primary School Nargi Jivnath Pmnsy Road to Nargi		
Scheme/Programme:	MAINTENANCE	Road Id No.:	mmusy (sc), Jagdish not. hu + 1440121
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	✓ No

Overall Rating :

Satisfactory (S)	✓ S ✓
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	✓

Ravi Kumar
(Signature)

NAME:

DESIGNATION: