FIELD INSPECTION REPORT

Division	: RWN	7:12:2020 District: Muzoffa East-1 Length (km): 1-187	-
Scheme/	Programme:	varika Nagaax to Rinda Fried	school Tax
Package		And the second s	The statement of the st
The second secon	f the Project:	Ongoing/Completed/Under Maintenance	t til der sette til state, film er flyste state til state til se ett state state til state til state til state
	a case of:	New Connectivity/Up gradation/ Maintenance	Thirt shapping and makes are and an amount of the same
SL No.		Parameters to be checked	Remarks
1.	Pavement		
a)	Road Junction condition		VS/U
b)	Condition of Surfacing		18/14
c)	Riding Quality		√s/U
d)	Road Camber		√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		osed Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		nting S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		√S/SRI/U
c)	Condition of railings/slab/approach for Bridges		√s/sri/u
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		
	And the second s	and the second of the second o	
Overall	Rating :	Satisfactory (S)	
		Satisfactory but requires Improvement (SI	U) SPT

(Signature)

NAME:

DESIGNATION: