FIELD INSPECTION REPORT

Date of Inspection: 17.12.2020 District: Muzaffar				(d	
Division: RWD. Fast-1			Length (km): 2-375		
Vame of	the Road: Ch	hapra Meg	h Manika PEO Rd to Da	kshin T	
Scheme/I	rogramme:	MAINTENANCE		Nacial metalogica participa y substitution (see	
			Road Id No.:	A STATE OF THE PARTY OF THE PAR	
THE RESIDENCE OF THE PROPERTY			ompleted/Under Maintexance ctivity/Up gradation/ Maintenance		
and the same of the same of	n case of:	A THE STATE OF THE	COMMENCE THAT I COMMING THE RESIDENCE OF THE SECOND	***	
St. No.	A STATE OF THE PROPERTY OF THE PARTY OF THE	Parameters to be checked Remark			
I.	Pavement				
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√8/U	
d)	Road Camber			√\$⁄U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Ves/No	
D	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
	Condition of Abutment & Wing walls, Slab in RCC culverts			√S/SRI/U	
b)	Condition of railings/slab/approach for Bridges			√8/SRI/U	
c)					
3.	Road Furniture			4	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Xes/No	
4.	Compliance History			-	
a)	Status of ATR's & any others				
Overall Rating : S		procede Gambathan rather alban a constitution and constit		5	
		Satisfactory	but requires Improvement (SRI)	and the second second	
		Satisfactory			

(Signature)

NAME:

DESIGNATION: