

FIELD INSPECTION REPORT

GTSNY

Date of Inspection :	16/12/2020	District:	Jammu
Division :	Jammu	Length (km):	0.500 Km
Name of the Road:	Masle Ravidas Tola To Harla Beldari PMGSY Road		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	20804101828
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SAT
b)	Condition of Surfacing	SAT
c)	Riding Quality	SAT
d)	Road Camber	SAT
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
16/12/2020

(Signature)

NAME:

DESIGNATION: