GTSNY.

FIELD INSPECTION REPORT

Date of I	ispection: 16/12/20	District: James	
		Length (km); 2.00 K	m
		Pandro Badrout PMGS	Road
	rogramme: MAINTENA		
Package No.:		Road Id No.: 2080 410	1829
		mpleted/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.		refacto be checked	Remarks
	Pavement		
a)	Road Junction condition		SÆ
b)	Condition of Surfacing		SÆ
c)	Riding Quality		S/ U
d)	Road Camber		SAJ
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
	To attack this light of		
a)	Condition of head walls in Hume pipe culverts including its painting		-S/SRIAU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/ SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.5	Rouk Sumilare		
a)	Whether sign boards/infor	matory/cautionary Board/km & 200m ings are provided and maintained	_ Yes /No
4. 州縣	reporting and one to the second of the secon		
a)	Status of ATR's & any other	rs.	NA

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

AE, Laxanjus

NAME:

DESIGNATION: