		FIELD INSPE	CTION REPORT	
Date of Divisio	f Inspection: -/ on: - f.w. D(w of the Road: S)	7/12/2020) air F.B. 5 107 Manturi :	District: - Aranga Length (km): 2 km tol9 to Ansam Toly	
Schem	e/Programme:	MAINTENANCE		
Packag	ge No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance Remarks		
Work is a case of:		New Connectivity/U	op gradadow wante	Remarks
Sl. No.		Parameters to	be checked	
1.	Pavement			0//1
a)	Road Junction condition			S/U
				S/U
b)	Condition of Surfacing			~S/U
c)	Riding Quality			VS/U
d)	Road Camber			N. Ola
e)	Whether free from defects such as visible cracks, exposed Yes/No aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			
	Compaction of flank/slope & raincuts if any			Yes/No
g)				
2.	Cross Drainage S/SRI/U			S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			- BIBICO
	Road Furniture			
3.			equtionary Board/km & 200m	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			100.1
4.	stones/Pavement road markings are provided Compliance History			
a)	Status of ATR's	& any others		,

Overall Rating :

	0
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) Ju

WHURLS I WAVE