## FIELD INSPECTION REPORT

Date of Inspection : - 18-12- 2020			District: Machubaul	
Division: Jaynagas			Length (km): - 0-40 KM	
Name of	the Road: -	Ram Bilagh yas	day We bihar be Mahendra y	aday Ke Gilya
Scheme/Programme: MAINTENANCE		MAINTENANCE	- GITSNY	
Package No.:			Road Id No.:	
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance		
MAIN CONTRACTOR	a case of:	New Connectivity	/Up gradation/ Maintenance	
Sl. No.		Parameters	to be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			SAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Yes/No			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
0)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No/
245	Compliance	History		
-		Self Control of the C		

Overall Rating :

a)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	

(Signature)

NAME: — Pam provid Rem DESIGNATION: - I-E

Status of ATR's & any others

PD IBINIZED