

FIELD INSPECTION REPORT

Date of Inspection :
 Division : Muzaffarpur East - 01 District: Muzaffarpur
 Name of the Road: Dardha Siho Path Mau Bhueya chaur to Umesh Umesh Jha Length (km): 1.428 KM
 Scheme/Programme: MAINTENANCE Ke ghoo PMGSY Path Tak
 Package No.:
 Status of the Project: Ongoing/Completed/Under Maintenance Road Id No.: 31507201354

Work is a case of:		Remarks
New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Shravan
 19.12.2020
 SE

(Signature)

NAME:

DESIGNATION: