FIELD INSPECTION REPORT

| Date | of Inspection: | 17/12/2020 | District: NAWAI | |
|--------|--|------------------------------|---|--|
| Divisi | on: Rf | JAULI | Length (km): 1.200 | • • |
| Name | of the Road: | JIRWATARI | | ARIJAN TO |
| | ie/Programme: | MAINTENANCE | / GTSNY | * 18/07 |
| | ge No.: | NA | | 01837 |
| | of the Project: | | /Under Maintenance In gradation/ Maintenance | |
| SI No | is a case of: | Parameters to | | Remarks |
| 1. | Pavement | in the last the state of the | Cold to the Cold | A Section of the sect |
| a) | Road Junction condition | | | S/U |
| b) | Condition of Surfacing | | | S/U |
| c) | Riding Quality | | | S/U |
| d) | Road Camber | | | S/U |
| c) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No |
| Ŋ | Contraction Joints provided or not (CC Pavement) | | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| | Gross Drainage | 1 | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U |
| ;) | Condition of railings/slab/approach for Bridges | | | S/SRI/U |
| | Road Furniture | | | |
|) 5 | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | |
| | Зотринее Ни | Jeg. | | |
| S | status of ATR's & | any others | | The state of the s |

Overall Rating

| Satisfactory (S) | "S" |
|---|-----|
| Satisfactory but requires Improvement (SRI) | -1 |
| Unsatisfactory (U) | - |

(Signature)

NAME: BINDA KUMAR

DESIGNATION: J. E, RWD.

Scanned with CamScanner