GTSNY

FIELD INSPECTION REPORT

Date of Inc	spection: 16	112/2020	District: Jamus	
ivision:	Jas	ขณ่	Length (km): 1.00 Km	
Name of th		Lamankyna	a Addinasi Tola -	To Ada
Scheme/P	rogramme:	MAINTENANCE	PMGSY RO	ad
Package N	No.:		Road Id No.: 208041019	835
	the Project:		/Under Maintenance	
Work is a	case of:		Jp gradation/ Maintenance	Engale Parket of the
\$1. No.	- Application	Parameters to	be checked	Remarks
	Pavement			W-1075
a)	Road Junction	condition		SAU
b)	Condition of Surfacing			SAU
c)	Riding Quality			SAU
d)	Road Camber			SAU
e)	Whether fre	e from defects su case of CC Pavemen	ch as visible cracks, exposed it.	Yes/ No
f)		Joints provided or not		YesAlo
g)	Compaction	of flank/slope & rain	cuts if any	Yes/ No
2.	Cross Drai	inge and state	THE SECOND SECOND	
a)	Condition o	f head walls in Hume	pipe culverts including its painting	-S/SRI/U
b)	Condition o	f Abutment & Wing w	valls, Slab in RCC culverts	S/SRI/U
c)	Condition o	f railings/slab/approac	ch for Bridges	SASRIVU
3.	Road Korn	fore		
a)	Whether sig	nent road markings a	ry/cautionary Board/km & 200m re provided and maintained	Yes /No
4	Compliance	History	AT LEMINORPHIC	A STATE
a)	Status of AT	R's & any others		NA

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	λ

DESIGNATION:

NAME:

(Signature)