

FIELD INSPECTION REPORT

NABARD

Date of Inspection : 14/12/2020	District: Jamui
Division : Jamui	Length (km):
Name of the Road: Kohbarba Jhagha PWD Asafa Oghadih To Pitraun	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: 20804100328
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SA✓
b)	Condition of Surfacing	SA✓
c)	Riding Quality	SA✓
d)	Road Camber	SA✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:

[Signature]
14/12/20

AE, Laxmipuz

(Signature)