## FIELD INSPECTION REPORT

te of Inspection: 14/12/2020		12/2020	District: Jamuel	
vision: Jaroui			Length (km): 1.393 K	<b>m</b> o
ame of th	e Road: LI.	41 - LU47	To Yadar Tola.	
heme/Pr	rogramme: M	AINTENANCE		
ackage N			Road Id No.: 208041002	225
			d/Under Maintenance	
Vork is a	case of:	. 1	Up gradation/ Maintenance	Contractor 1
Sl. No.	A STATE OF THE STA	Parameters t	be drecked.	Remarks
1.	Pavement			
a)	Road Junction condition			SÆ
b)	Condition of Surfacing			SÆ
c)	Riding Quality			SA
d)	Road Camber			SA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/ <del>No</del>
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			YesAlo
	Cross of Falling	Collins with		i velika i
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.7	Routstanture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			YesAlo
	Compliants at story a			1,2
a)	Status of ATR's & any others			NA

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME:

DESIGNATION: