FIELD INSPECTION REPORT

		District: James	
No Sec. 10	Igmui	Length (km): 0.753	Km
ne Road:	143-703 2	road to Gosai	TOA
rog ramme :	MAINTENANCE		
lo.: '			0226
case of:	THE PROPERTY OF THE PERSON HEADS		
Section of the second	Parameters to	all arread to the Transition of the Control of the	Remarks
Pavement			and the standard of the standa
Road Junction condition			SAU
Condition of Surfacing			SAU
Riding Quality			SAU
Road Camber			SÆ
Whether free from defects such as visible cracks, exposed			Yes/ No
Contraction Joints provided or not (CC Pavement)			YesANo
Compaction of flank/slope & raincuts if any			Xes/No
entorin	HgC Classic Process		
Condition of head walls in Hume pipe culverts including its painting			- S/ SRI/ U
			S/ SRI/U
Condition of railings/slab/approach for Bridges			S/SRI/U
	ure		
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			" Yes /No
(compliants)	Witney in 1982	CONTROL OF THE PROPERTY OF THE	
Status of ATR's & any others			N.A
The state of the s	rogramme: lo.: the Project: case of: Pavement Road Junction Condition of S Riding Qualit Road Camber Whether fre aggregates in Contraction Compaction Compaction Condition of	he Project: Ongoing/Completed case of: New Connectivity/L Parameters to Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects surfaction Joints provided or not Compaction of flank/slope & raince Cross Draininge Condition of head walls in Hume p Condition of Abutment & Wing was Condition of railings/slab/approach Road Furniture Whether sign boards/informatory, stones/Pavement road markings are Compilance History Compilance History	MAINTENANCE O.: Road Id No.: 20804/O the Project: Ongoing/Completed/Under Maintenance case of: New Connectivity/Up gradation/ Maintenance Paramaters to the checked Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Cross Draininge Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Compliance History

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

14112 200 MATIZIAND

(Signature)

NAME:

DESIGNATION: