

FIELD INSPECTION REPORT

Date of Inspection :	18.12.2020	District:	Samen (Chhapra)
Division :	Madhubani	Length (km):	0.200 km
Name of the Road:	Bachan P.M.G. Path se Jagdis Singh ke Dahan Se thakke se Rugh Wagha Jale.		
Scheme/Programme:	MAINTENANCE	Road Id No.:	3130650/845
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Remarks
Sl. No.	Parameters to be checked		
1.	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		N/A
a)	Status of ATR's & any others		N/A

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Flank minor C.I. Partly.

(Signature)

NAME: Abdul Matin Khan

DESIGNATION: J.E.