

FIELD INSPECTION REPORT

Date of Inspection : 12/12/20	District: Siron (Chapra)
Division : Madhwa	Length (km): 0.300 km
Name of the Road: Arunachal Pradesh Road No. 110, Vidyachakra Madhwa Co. Road, Chapra	
Scheme/Programme: MAINTENANCE	Road Id No.: 3/3/450/250
Package No.:	
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/L
b)	Condition of Surfacing	S/L
c)	Riding Quality	S/L
d)	Road Camber	S/L
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Not
4.	Compliance History	
a)	Status of ATR's & any others	N.O.

Rating :

Satisfactory (S)	N/O
Satisfactory but requires Improvement (SRI)	✓ SRI
Unsatisfactory (U)	N/O

Block cutting due to Heavy Rain & Flood.

(Signature)
(Signature)

NAME: Arunachal Madhwa

DESIGNATION: J.E.