

FIELD INSPECTION REPORT

Date of Inspection :	18/12/2020	District:	MV2.
Division :	R.W.D MV2 east 7	Length (km):	1.484 km
Name of the Road:	Bachilwara Rupnath Paleki Sadak to Madhy		
Scheme/Programme:	MAINTENANCE	mmusy (se)	vidyalay annual.
Package No.:		Road ID No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ S
f)	Contraction Joints provided or not (CC Pavement)	✓ S
g)	Compaction of flank/slope & raincuts if any	✓ S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S
c)	Condition of railings/slab/approach for Bridges	✓ S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 2 stones Pavement road markings are provided and maintained	✓ S
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Pratik Kumar
18/12/2020
(Signature)

NAME:

DESIGNATION: