

FIELD INSPECTION REPORT

Date of Inspection : 18/12/2020 District: MV2
 Division: R.W. 3 MV2 East Length (km): 1.785
 Name of the Road: NH102 omkar sharma kemil to lalgauya
 Scheme/Programme: MAINTENANCE pitch Road
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
1.1	Road Junction condition	✓ S/U
1.2	Condition of Surfacing	✓ S/U
1.3	Riding Quality	✓ S/U
1.4	Road Camber	✓ S/U
1.5	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
1.6	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
1.7	Completion of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
2.1	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
2.2	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
2.3	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
3.1	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
4.1	Status of ATR's & any others	- No -

Overall Rating :

Satisfactory (S)	- S -
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Ravi Kumar
 (Signature) 18/12/2020

NAME:

DESIGNATION: