## FIELD INSPECTION REPORT

		TIEDD HATEL	TION REPORT		
Date of Inspection: 17/17/10			District: Arondy		
Division: - Rom-D(m) ain F-B-4			Length (km): 3.2 km		
Name	of the Road: -	miszabur to	Herrison Tola		
Schem	c/Programme:	MAINTENANCE			
Package No.:			Roud Id No.:		
Status of the Project:		Ongoing/Completed/Under Maintenauce			
Work is a case of:		New Connectivity/Up gradation/ Maintenance  Remarks			
Sl. No.	No. Parameters to be checked		be checked	Remarks	
1.	Pavement				
a)	Road Junction	S/U			
b)	Condition of Surfacing			5/U	
c)	Riding Quality			VS/U	
	Road Camber			VS/U	
d) e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
n	Contraction Joints provided or not (CC Pavement)  Wes/No			Yes/No	
	Compaction of flank/slope & raincuts if any  Yes/No			Yes/No	
g)	Cross Drainage				
2	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
a)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
b)	Condition of railings/slab/approach for Bridges			_S/SRI/U	
c)	Road Furniture				
3,	The state of the s				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others				

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) J6

NAME:	