FIELD INSPECTION REPORT

Date of	Inspection: 16	19. 2120 District: Myzaffysty	
DIVISIO	11: Myzafta	Spyc Fast nt Length (km): 1 and	
· · · · · · · ·	n the Road: A	elgasta Purana RCD Pitch sound to	Kumer
Scheme	Programme:	MAINTENANCE Ram Vilash Pandi	f keglyot
Packag		Road Id No.: 31507201	353
		Ongoing/Completed/Under Maintenance	,
1	ork is a case of: New Connectivity/Up gradation/ Maintenance		
SI. No.		Parameters to be checked	Remarks
1.62	Pavement.		
a)	Road Junction	Road Junction condition	
b)	Condition of Surfacing		51
c)	Riding Quality		×1
d)	Road Camber		51
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
1)	Contraction Joints provided or not (CC Pavement)		Yes'No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI'U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furnitur		3/31(//)
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		√Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		
Overall F	Rating .		
		Satisfactory (S)	
		Satisfactory but requires Improvement (SRI)	e A
		Unsatisfactory (II)	SRI

NAME:

DESIGNATION:

17.12.2020 JE

(Signature)

Scanned with CamScanner