

## FIELD INSPECTION REPORT

Date of Inspection-	19-12-20	District Patna
Division-	Danapur	Length (KM) 6.5 KM
Name of Road-	Bihla Shivala PWD Rd to Sadishapur	
Scheme/Programme-	Maintenance Head 3054	
Package no.-	Road Id No.	
Status of the Project	On going/Complete/Under Maintenance	
Work is a case of	New Connectivity/Up gradation/Maintenance ✓	
sl no.	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a	Road Junction Condition	✓S/U
b	Condition of Surfacing	S/U ✓
c	Riding Quantity	S/U ✓
d	Road Camber	✓S/U
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓
f	Contraction joints provided or not (CC Pavement)	Yes/No ✓
g	Compaction of flank/slope & raincuts if any	Yes/No ✓
<b>2</b>	<b>Cross Drainage</b>	
a	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U ✓
c	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
<b>3</b>	<b>Road Furniture</b>	
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓
<b>4</b>	<b>Compliance History</b>	
a	Status of ATR's & any others	

Overall Rating:

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Note:- 1. Notice issued to contractor.  
2. work not started.

Name

Fr. Yogeshwar Pandey  
CE-2

Signature  
C.E-2

20/12/20