

FIELD INSPECTION REPORT

Date of Inspection-	19-12-2020	District	Patna
Division- <i>Danapur</i>		Length (KM)	1.05 KM
Name of Road-	<i>Chakardaha More to Naukratanpur</i>		
Scheme/Programme-	Maintenance Head 3054		
Package no.-		Road Id No.	
Status of the Project	On going/Complete/Under Maintenance ✓		
Work is a case of	New Connectivity/Up gradation/Maintenance ✓		

sl no.	Parameters to be Checked	Remarks
1	Pavement	
a	Road Junction Condition	S/U ✓
b	Condition of Surfacing	S/U ✓
c	Riding Quantity	S/U ✓
d	Road Camber	S/U/SRI ✓
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f	Contraction joints provided or not (CC Pavement)	Yes/No
g	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U
c	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓
4	Compliance History	
a	Status of ATR's & any others	

} NA

} NA

Overall Rating:

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

Note:- 1. Notice issued to contractor
 2. work not started.
 3. village portion badly damaged.

Name

Er. Yogeshwar Pandey

CE-2

19-12-20
 Signature
 C.E-2