

## FIELD INSPECTION REPORT

Date of Inspection-	19-12-20	District	Patna
Division-	Danapur	Length (KM)	9.7 KM
Name of Road-	Lodipur NH 30 to Sadiapur near Panal Petrol Pump		
Scheme/Programme-	Maintenance Head 3054		
Package no.-	Road Id No.		
Status of the Project	On going/Complete/Under Maintenance		
Work is a case of	New Connectivity/Up gradation/Maintenance		
sl no.	Parameters to be Checked		Remarks
1	<b>Pavement</b>		
a	Road Junction Condition		S/U
b	Condition of Surfacing		S/U/SRI
c	Riding Quantity		S/U
d	Road Camber		S/U
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f	Contraction joints provided or not (CC Pavement)		Yes/No
g	Compaction of flank/slope & raincuts if any		Yes/No
2	<b>Cross Drainage</b>		
a	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b	Condition of Abutment & Wing walls, Slab in RCC Culverts		S/SRI/U
c	Condition of railings/slab/approach for Bridges		S/SRI/U
3	<b>Road Furniture</b>		
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained		Yes/No
4	<b>Compliance History</b>		
a	Status of ATR's & any others		

Overall Rating:

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Note:- 1. Notice issued  
 2. Work started for grass trimming.  
 3. material being stacked.

Name

Er. Yogeshwar Pandey  
 CE-2

19.12.20  
 Signature  
 C.E-2