		FIELD INSPECTI	ON REPORT	
Date of Inspection-		19-12-2020	District Patr	a
Division-		19-12-2020 Danapus	District Patna Length (KM) 3.2 KM	
Name of Road-		Belatchaura Gopalpur Laxmanbur Road Maintenance Head 3054		us Road
Scheme/Programme-		Maintenance Head 3054		
Package no		Road Id No.		
Status of the Project		On going/Complete/Under Maintenance		
Work is	a case of	New Connectivity/Up gr	adation/Maintenance	
sl no.		Parameters to be	Checked	Remarks
1	Pavement		The second of the second	2011
а	Road Junction C	oad Junction Condition		
b	[Collution of Surfacing			S/U/SR
С	Riding Quantity			1 8/U
d	Road Camber			187 U
е	Whether free from defects such as visible cracks, exposed aggregates in			in Yes/Nov
	case of CC Pavement			V/VIII
f	Contraction joints provided or not (CC Pavement) Yes/No			
g	Compaction of	Compaction of flank/ slope & raincuts i f any Yes/No		
2	Cross Drainage			
а	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b	Condition of Abutment & Wing walls, Slab in RCC Culverts S/SRI/U			
С	Condition of railings/slab/approach for Bridges S/SRI/U			
3	Road Furniture		- 1/4010 000	V/N /
а	Whether sign board/informatory/cautionary Board/KM & 200 m			Yes/No 🗸
	stones/Pavement road markings are provided and maintained			The state of the s
4	Compliance Hi	Compliance History		
а	Status of ATR's & any others			
	Overall Rating:	Satisfactory (S)		_
		Satisfactory but requir	es Improvement (SRI)	SRI
		Unsatisfactory (U)		-
Note:	- 1. Notice issued		21	
	1. Notice issued 2. work not storted		Carp 10	
				Signature
	Name	shwar Pandey CE-2		C.E-2
	CL. Yoge	shwar Pandeyt		
		CE-2-		