

FIELD INSPECTION REPORT

Date of Inspection : 20/12/2020	District: Samastipur
Division : Daluighat	Length (km): 6.5
Name of the Road: Rewari dhala to Chaiba Pmssy Paly	
Scheme/Programme: MAINTENANCE	New mile
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	on going
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	- S/U
b)	Condition of Surfacing	- S/U
c)	Riding Quality	- S/U
d)	Road Camber	- S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	- Yes/No
f)	Contraction Joints provided or not (CC Pavement)	- Yes/No
g)	Compaction of flank/slope & raincuts if any	- Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	- S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	- S/SRI/U
c)	Condition of railings/slab/approach for Bridges	- S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	- Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	U

The completion period Expired. The contractor has not started the work. Action against contractor as per MBD clause has been directed.

Samir Kumar
(Signature) 20/12/2020

NAME: Samir Kumar

DESIGNATION: F.E