FIELD INSPECTION REPORT

Date of Inspection: 20.12.2020	District : Bhagalpur
Division : Bhagalpur	Length (km): 2.3
Name of Road : Sarha to Bhikhanpur	
Scheme/Programme : New Maintenance P	olicy 2018
Package No.: 11	Road Id No.: 27321032919
Status of the Project : Ongoing	

Work is a case of : Up gradation

SI. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	NA	
b)	Condition of Surfacing	NA	
c)	Riding Quality	NA	
d)	Road Camber	NA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA	
f)	Contraction Joints provided or not (CC Pavement)	NA	
g)	Compaction of flank/slope & raincuts if any	NA	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	
c)	Condition of railings/slab/approach for Bridges	NA	
3	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	No	
4	Compliance History		
a)	Status of ATR's & any others: Only Trench Cutting Foundation of the Bridge was seen.		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	U
Unsatisfactory (U)	

NAME: KUMAR RAKESH

DESIGNATION: EXECUTIVE ENGINEER

(Signature)