

FIELD INSPECTION REPORT

Date of Inspection : 20.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (km) : 2.5	
Name of Road : Mahto Sthan to Sarha			
Scheme/Programme : New Maintenance Policy 2018			
Package No. : 11		Road Id No.: 27321032926	
Status of the Project : Ongoing			
Work is a case of : Up gradation			
Sl. No.	Parameters to be checked		Remarks
1	Pavement		
a)	Road Junction condition		NA
b)	Condition of Surfacing		NA
c)	Riding Quality		NA
d)	Road Camber		NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		NA
f)	Contraction Joints provided or not (CC Pavement)		NA
g)	Compaction of flank/slope & raincuts if any		NA
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		NA
c)	Condition of railings/slab/approach for Bridges		NA
3	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained		Yes
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER

(Signature)

[Handwritten Signature]
20.12.2020