FIELD INSPECTION REPORT

Date of Inspection: 19/12/www District: Grayer				THE SECOND IS NOT THE COMPANY AND ADDRESS OF THE SECOND SE
Division: shergheti Length (km): 2.30 km				
Name of the Road: GT Road to Reganizer.				
Scheme/Programme: MAINTENANCE				
Package No.: Road Id No.:				
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		All Marie and All All All All All All All All All Al
Sl. No.	A Section of the sect		Remarks	
1,				
a)	Road Junction	condition	√S/IJ	
b)	Condition of Surfacing			SAU
c)	Road Junction condition Condition of Surfacing Riding Quality Road Camber			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			M A Yes No
f)	Contraction Joints provided or not (CC Pavement)			NA Yes/No
g)	Compaction of flank/slope & raincuts if any			No Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting 104 SSRIFE			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts NA S/SRI/U			
c)	Condition of railings/slab/approach for Bridges No. S/SRL/U			
3.	Road Furniture			
a) .	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained			
4. Compliance History				1
a)	Status of ATR's & any others			No
	The same of the sa	No work P	rogress	,
Overall Rating :		Satisfactory (S)	A /CFY	
Satisfactory but requires Improvement (SRI)				
Unsatisfactory (U)			U	

(Signature)

NAME: Si Kant Prascol.

DESIGNATION: E-E-