


FIELD INSPECTION REPORT

Date of Inspection: 19/12/2020	District: KISHANGANJ
Division: KISHANGANJ-I	Length(km): 5.94 KM
Name of the Road: TOS - HANDEBHASA TO JHANTIBARI	
Scheme/Programme: NEW MR	
Package No.: RM/KI/KIS/19/0007	Road Id No.:
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance	
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/ Up gradation / Maintenance	

Sl. No	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank / shop & raincuts if any	Yes/No ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCG culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	*


 19/12/20
 (Signature)

NAME: E. CHANDRASHEKHAR AZAD
 E.E.