

FIELD INSPECTION REPORT

Date of Inspection :- 19.12.20		District :- Kishanganj
Division :- Kishanganj-I		Length (km) :- 6.00 KM
Name of the Road :- L60 - T03 to Dubadanga (VR60)		
Scheme/Programme :- MAINTENANCE (N.M.P)		
Package No. :- MR-N/19.20/Kishanganj-I/6		Road Id No. :- 21205802058
Status of the Project :- Ongoing/Completed/Under Maintenance		
Work is a case of :- New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N.A	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement) - N.A	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others ND ATR	Pending

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

19/12/20
(Signature)
(E.E.)

NAME :- Er. Chandrashekhar Azad
(E.E.)