

FIELD INSPECTION REPORT

Date of Inspection:	19/12/2020	District:	KISHANGANJ
Division:	KISHANGANJ-I	Length(km):	3.250 km
Name of the Road:	SHITALNAGAR TO 6 TO PURANDHA		
Scheme/Programme:	NEW MR		
Package No.:	RM/KI/KIS/19/0002	Road Id No.:	-
Status of the Project:	Ongoing/Completed /Under Maintenance		
Work is a case of:	New Connectivity/ Up gradation / Maintenance		

S1. No	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank / shop & raincuts if any	Yes/No on going
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No on going
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

19/12/20
(Signature)

NAME: E. CHANDRASHEKHAR AZAD
E.E.