## FIELD INSPECTION REPORT

Date o	f Inspection:	9 12 2020	District: KIGHANGANI	
Divisio	n: KISHANG	ANT-1	Length(km): 2.36 km	
	of the Road:	TENA BRI	GE TO SHAHANGAON .	
Scheme	e/Programme:	NEW MR		· ·
Packag		E/KIS/19/000	Road Id No.:	
	of the Project:	Ongoing/Compl	eted/Under Maintenance	
Nork is a case of: New Connectivity/ Up gradation / Maintenance			Danianka	
\$1. No		Parameters to be checked,		Remarks
1.	Pavement			√S/U
a)	Road Junction Condition			VS/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			VS/U
d)	Road Camber			✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints Provided or not (CC Pavement)			Yes/No
g)	Compaction of flank / shop & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCG culverts			S/SRI/U
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Yes/No
	stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			Mo

Overall Rating:

Satisfactory(S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory(U)

(Signature)

NAME: Ex. CHANDRASHEKHAR AZAD

E.E.