## FIELD INSPECTION REPORT

Date o	f Inspection:	12 2020 District: KISHANGANJ	
Divisio			
	of the Road:	ITIHA TOG TO SINGHARI	,
	e/Programme:	NEW MR	
Windows Street, Canada Street, Brownson,	ge No .: RM/K	E/KIS/19/0007 Road Id No.: -	
	of the Project:	Ongoing/Completed/Under Maintenance	
	s a case of:	New Connectivity/ Up gradation / Maintenance	
\$1. No	Parameters to be checked,		Remarks
1.	Pavement		
a)	Road Junction Condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		√S/U Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints Provided or not (CC Pavement)		
g)	Compaction of flank / shop & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		
b)	Condition of Al	S/SRI/U	
c)	Condition of ra	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating:

Satisfactory(S)	3'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: Ex. CHANDRASHEKHAR AZAD

E.E.