

FIELD INSPECTION REPORT

Date of Inspection : 19/12/20	District: East Champaran	
Division : Chakiya	Length (km): 2.08	
Name of the Road: R.E.D Road to Benipur		
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.: 31708202190	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance	New M/D	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of Bank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards informative/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	NA
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	S
Satisfactory but Requires Improvement (SRI)	✓
Unsatisfactory (U)	✓

[Signature]
(Signature)

NAME: Bindu Rajak

DESIGNATION: Executive Engineer
R.W.D.

Regional Laboratory Darbhanga