

FIELD INSPECTION REPORT

Date of Inspection :	19/12/20	District:	East Champaran
Division :	Chakya	Length (km):	9.10
Name of the Road:	P.P.GA NH 28 To Kalyanpur RD Road.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	81708408016
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance New MTK		

Sl.No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but Requires Improvement (SRI)	
Unsatisfactory (U)	

6.00km S.D.B-C done work is in progress

(Signature) 19/12/20

NAME: Bindu Rajak

DESIGNATION: Executive Engineer

R.W.D.
Regional Laboratory Darbhanga