

### FIELD INSPECTION REPORT


Date of Inspection : 19.12.2020		District : Bhagalpur
Division : Bhagalpur		Length (km) : 16.05
Name of Road : Repair of road from Shivshankar Mor to Kajraili via Sajaur Radhanagar		
Scheme/Programme : OLD MR		
Package No. :		Road Id No.: 20703208228
Status of the Project : Under Maintenance		
Work is a case of : Up gradation		
Sl. No.	Parameters to be checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	No
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRI
c)	Condition of railings/slab/approach for Bridges	SRI
<b>3</b>	<b>Road Furniture</b>	
a)	Whether <b>sign board</b> /informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	Yes
<b>4</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	<b>SRI</b>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER

  
 (Signature) 19.12.2020