

FIELD INSPECTION REPORT

| | | | |
|-------------------------|--|---------------|---------------------|
| Date of Inspection : | 18/12/2020 | District : | Munger |
| Division : | Munger | Length (Km) : | 1.0 KM |
| Name of the Road : | Repair of road from Jamal Dharbasa main road to house of Naresh Paswan via Samudraich Bhanu | | |
| Scheme/Programme : | MAINTENANCE MR (BOSY) | | |
| Package No. : | | Road Id No. : | 20803708163 |
| Status of the Project : | Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/> | | |
| Work is a case of : | New Connectivity/Up gradation/Maintenance <input checked="" type="checkbox"/> | | |
| Sl. No. | Parameters to be checked | Remarks | |
| 1 | Pavement | | |
| a) | Road Junction condition | S/U | |
| b) | Condition of Surfacing | S/U | |
| c) | Riding Quality | S/U | |
| d) | Road Camber | S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No | exposed Aggregates. |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | Yes/No | |
| 2 | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U | NA |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U | |
| 3 | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained | Yes/No | |
| 4 | Compliance History | | |
| a) | Status of ATR's & any others | NA | |

Overall Rating :

| | |
|---|-----|
| Satisfactory (S) | 1 |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U) | 1 |

NAME : RATIV RANJAN KUMAR
DESIGNATION : EE

Ratib Ranjan Kumar
(Signature)