


FIELD INSPECTION REPORT

Date of Inspection: 19/12/2020		District: KISHANGANJ	
Division: KISHANGANJ-1		Length(km): 3.500 km	
Name of the Road: REPAIR OF ROAD FROM HIMMATNAGAR CHAUK TO BHAWANIGANJ (MR)			
Scheme/Programme: MR			
Package No.: -		Road Id No.: -	
Status of the Project:		Ongoing/Completed /Under Maintenance ✓	
Work is a case of:		New Connectivity/ Up gradation / Maintenance ✓	

Sl. No	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. NA	Yes/No
f)	Contraction Joints Provided or not (CC Pavement) NA	Yes/No
g)	Compaction of flank / shop & raincuts if any NA	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCG culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges NA	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	


 19/12/20
 (Signature)

NAME: E. CHANDRASHEKHAR AZAD
 E.E.