

FIELD INSPECTION REPORT

Date of Inspection : 19/12/20	District: East Champaran
Division : Chakia	Length (km): 1.00
Name of the Road: SH 74 Torharpur Road	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 31708408041
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	old M/R

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	—
Satisfactory but Requires Improvement (SRI)	—
Unsatisfactory (U)	U

NAME:

Bindu Rajak

DESIGNATION:

Executive Engineer
R.W.D.
Regional Laboratory Darrbhanga

19/12/20
(Signature)