

FIELD INSPECTION REPORT

Date of Inspection :	18.12.2020	District :	Munger
Division :	Munger	Length (Km) :	0.285 KM
Name of the Road :	NH-80 Bahachodei Mandir to Munnaji ke Gher Holz Hua Mukhiya ke Ghar Tak Path Nirman.		
Scheme/Programme :	MAINTENANCE MR (3054)		
Package No. :		Road Id No. :	20803700853
Status of the Project :	Ongoing/Completed/Under Maintenance ✓		
Work is a case of :	New Connectivity/Up gradation/Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓U	
d)	Road Camber	✓S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	exposed aggregate, visible
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	} NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4	Compliance History		
a)	Status of ATR's & any others	NA	

Overall Rating :

Satisfactory (S)	/
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	✓

NAME : RAJIV RANJAN KUMAR
DESIGNATION : EE

Rajiv Ranjan Kumar
(Signature)