FIELD INSPECTION REPORT

| Date of | Inspection: | | and the second s | |
|--|--|---|--|-----------|
| Division: St. District: Graya | | | | |
| Length (km): | | | | |
| Salar on She khap Gruis Road to pa chapt (471) | | | | |
| Package No: | | | | |
| Road Id No.: | | | keri kera pundi (n. 1975), ilm gine guna jang akan keranggangan ak <mark>angan tahu</mark> n kerant (n. 1949). | |
| The state of the s | | This can be a second and the second | | |
| Sl. No. | The Connectivity of gradation Maintenance | | | |
| | | Parameters to be checked Remarks | | |
| 1. | Pavement | | | |
| a) | Road Junction condition S/U | | | |
| b) | Parameters to be checked Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks exposed | | | S/U |
| e) | Riding Quality | | | S/U |
| d) | Road Camber S/U | | | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | |
| f) | Contraction Joints provided or not (CC Pavement) | | | M/Yes/No |
| g) | Compaction of flank/slope & raincuts if any RAYes/No | | | HA Yes/No |
| 2. | Cross Drainage | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting MAS/SRL/U | | | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts NAS/SRI/U | | | |
| c) | Condition of railings/slab/approach for Bridges NA S/SRI/U | | | |
| 3. | Road Furniture | | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained sign board bit uncomplete | | | Yes/No |
| 4. | Compliance History | | | |
| a) | Status of ATR's & any others | | | NO |
| Overall I | Rating : | Satisfactory (S) | , (SDI) | |

| | ASS Excellent marketing the property of the pr |
|--------------|--|
| Satisfactory | (S) |
| Satisfactory | but requires Improvement (SRI) |
| Unsatisfacto | ry (U) |

(Signature)

NAME:

Sin learn't prused

DESIGNATION:

E.E.