

# FIELD INSPECTION REPORT

|                                        |                                            |
|----------------------------------------|--------------------------------------------|
| Date of Inspection : 19/12/2020        | District: Gaya                             |
| Division : Sherghati                   | Length (km): 3.30 km                       |
| Name of the Road: GT Road to Kourmatha |                                            |
| Scheme/Programme:                      | MAINTENANCE New                            |
| Package No.:                           | Road Id No.:                               |
| Status of the Project:                 | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                     | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks    |
|---------|----------------------------------------------------------------------------------------------------------------------|------------|
| 1.      | <b>Pavement</b>                                                                                                      |            |
| a)      | Road Junction condition                                                                                              | S/U ✓      |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U      |
| c)      | Riding Quality                                                                                                       | ✓ S/U      |
| d)      | Road Camber                                                                                                          | ✓ S/U      |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | NA Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | NA Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | NA Yes/No  |
| 2.      | <b>Cross Drainage</b>                                                                                                |            |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | NA S/SRI   |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | NA S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | NA S/SRI/U |
| 3.      | <b>Road Furniture</b>                                                                                                |            |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No   |
| 4.      | <b>Compliance History</b>                                                                                            |            |
| a)      | Status of ATR's & any others                                                                                         | NO         |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          |     |

19/12/2020  
(Signature)

NAME: Sri Kant Prasad

DESIGNATION: E.E.