FIELD INSPECTION REPORT

Date of Inspection: 20.12.2020	District : Bhagalpur	
Division : Bhagalpur	Length (km): 1.45	
Name of Road: Pachrukhi P.W.D. to Goura	а	
C. L /D	La. 2018	

Scheme/Programme : New Maintenance Policy 2018

Package No.: 07 Road Id No.: 20703201031

Status of the Project : Ongoing

Work is a case of : Up gradation

SI. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	SRI
b)	Condition of Surfacing	SRI
c)	Riding Quality	SRI
d)	Road Camber	SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NA
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	Yes
4	Compliance History	
a)	Status of ATR's & any others : Pot Patching and GrIII in Progress	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

ESH
(Signature) (Signature)

NAME: KUMAR RAKESH

DESIGNATION: EXECUTIVE ENGINEER