

FIELD INSPECTION REPORT

Date of Inspection : 19.12.2020		District : Bhagalpur
Division : Bhagalpur		Length (km) : 3.75
Name of Road : Shahkund fulwria REO Road Yatrished to Ibrahimpur via chara Bargaon (Part-2)		
Scheme/Programme : New Maintenance Policy 2018		
Package No. : 09		Road Id No.: 20703301024
Status of the Project : Ongoing		
Work is a case of : Up gradation		
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	SRI
b)	Condition of Surfacing	SRI
c)	Riding Quality	SRI
d)	Road Camber	SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NO.
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	NA
4	Compliance History	
a)	Status of ATR's & any others :	NO.

Overall Rating :

Satisfactory (S)	U
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER

(Signature)

19.12.2020