


FIELD INSPECTION REPORT

Date of Inspection: 19/12/2020	District: KISHANGANGJ
Division: KISHANGANGJ-1	Length(km): 4.62 km
Name of the Road: PATKOI KHURD TO LODHNA CHOWK	
Scheme/Programme: NEW MR	
Package No.: RM/KI/KIS/19/0002	Road Id No.: -
Status of the Project: ☒ Ongoing/Completed /Under Maintenance	
Work is a case of: ☒ New Connectivity/ Up gradation / Maintenance	

S1. No	Parameters to be checked	Remarks
1.	Pavement	✓S/U
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank / shop & raincuts if any	Yes/No ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCG culverts	S/SRI/U N/A
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ongoing
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	


 19/12/2020
 (Signature)

NAME: E. CHANDRASHEKHAR AZAD

E. E