FIELD INSPECTION REPORT

Date o	finspection: 19/12/2020 District: KISHANGANJ	
Divisio		
The second secon	of the Road: / AIKANTA TO MAHTNGAON	
Schem	e/Programme:	
Packag	e No.: RM/KT/ KTS/19/0002 Road Id No.: -	
Status	of the Project: Ongoing/Completed /Under Maintenance	
Work is	s a case of: New Connectivity/ Up gradation / Maintenance	,
51. No	Parameters to be checked,	Remarks
1.	Pavement	VS/U
a)	Road Junction Condition	√S/U
b)	Condition of Surfacing	VS/U
c)	Riding Quality	VS/U
d)	Road Camber	√s/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No
g)	Compaction of flank / shop & raincuts if any on going	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCG culverts on going	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained on going	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating:

Satisfactory(S)

Satisfactory but requires Improvement (SRI)
Unsatisfactory(U)

*

(Signature)

NAME: Ex. CHA NDKASHEKHAR AZAD

E.E.